

# Final Reclamation Inspection

March 23, 2026

Operator: PDC ENERGY INC

Location ID: 418341

Inspection Document #: 720300210

Weld County, CO

Isaac Thibedeau  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: LUCCI B/01-69HNL  
Location ID: 418341



**Photo 1.** Photo taken from the location showing well sign.



## Inspection Photos

Location Name: LUCCI B/01-69HNL

Location ID: 418341



**Photo 2.** Photo taken of the location topsoil stockpile to the west of the location. Most of the pile is unvegetated and has evidence of rill erosion on it.



**Photo 3.** Photo taken of the location stockpile to the west of the location. See comments under photo 2.



Inspection Photos  
Location Name: LUCCI B/01-69HNL  
Location ID: 418341



**Photo 4.** Photo taken of the location stockpile to the west of the location. See comment under photo 2.



**Photo 5.** Photo taken of the location stockpile to the west of the location. See comment under photo 2.

Inspection Photos  
Location Name: LUCCI B/01-69HNL  
Location ID: 418341



**Photo 6.** Photo taken from the disturbance area on the northern end showing fencing is in disrepair around excavation.



**Photo 7.** Photo taken from the northern end of the disturbance showing that the fencing is in disrepair.