

# Inspection Photos

04/09/2026

**Operator:** TEP Rocky Mountain LLC #96850

**Location ID:** 427776

**Inspection Doc:** 719201049

Garfield County, CO

Emily Gaasche  
NW Reclamation Specialist  
ECMC



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

## Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 427776



**Photo 1:** Photos showing an overview of the location looking north and south, respectively.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 427776



**Photo 2:** Photos showing an overview of the location looking east and west, respectively.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 427776



**Photo 3:** Vegetation is not uniform at the east-central portion of the location; erosion and rilling is occurring in bare areas.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 427776



**Photo 4:** Erosion, soil tunneling and rilling is occurring underneath around straw hay bales used as stormwater controls at the location; maintenance is required. Comply with Rule 1002.f.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 427776



**Photo 5:** Photos showing straw wattles that are laden with sediment and straw bales with erosion cutting around them. Maintenance is required; comply with Rule 1002.f.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 427776



**Photo 6:** Photos showing the northern hillside is predominantly prickly Russian thistle (grey material), an undesirable annual plant species.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 427776



**Photo 7:** Photos showing the access road leading to the location has been reclaimed pursuant to 1004 reclamation requirements. The access road is used by cattle.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources