


Inspection Photos
Location Name: UPRR 24 PAN AM C#2
Location ID: 319935



PHOTO#1 WELLHEAD

PHOTO#2 SEPARATOR/GAS METER

Inspection Photos
Location Name: UPRR 24 PAN AM C#2
Location ID: 319935



PHOTO#3 PRODUCTION TANK

PHOTO#4 CA:TRASH ON LOCATION

Inspection Photos
Location Name: UPRR 24 PAN AM C#2
Location ID: 319935



PHOTO#5 CA:TRASH ON LOCATION