

# Inspection Photos

API: 071-07711

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 4/1/2026

County: LAS ANIMAS



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing southeast at the beginning of the access road.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

API:071-07517 | Date: 4/1/2026

## Inspection Photos



**Photo 2.** Facing southeast along the access road.



## Inspection Photos



**Photo 3.** Facing south along the access road.



## Inspection Photos



**Photo 4.** Facing southeast toward the reclaimed access road.



## Inspection Photos



**Photo 5.** Facing east toward the location.



## Inspection Photos



**Photo 6.** Facing east at the north side of the location. This area has not established sufficient perennial vegetation.



## Inspection Photos



**Photo 7.** Facing east along the fill slope of the location. This area has not established sufficient perennial vegetation.



## Inspection Photos



**Photo 8.** Southeast corner facing north. This area approximately 50ft by 30ft has insufficient vegetation cover.



## Inspection Photos



**Photo 9.** South side of the location facing west.



## Inspection Photos



**Photo 10.** Facing southeast toward the surrounding reference area.

