

# Inspection Photos

04/16/2026

**Operator:** Matrix Oil Corporation #10402

**Location ID:** 428755

**Inspection Doc:** 719201054

Rio Blanco County, CO

Emily Gaasche  
NW Reclamation Specialist  
ECMC



**COLORADO**


**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: Matrix Oil Company #10402

Location ID: 428755



**Photo 1:** Photos showing an overview of the location looking north and east, respectively.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: Matrix Oil Company #10402

Location ID: 428755



**Photo 2:** Photos showing an overview of the location looking northeast and west, respectively.



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

## Inspection Photos

Operator Name: Matrix Oil Company #10402

Location ID: 428755



**Photo 3:** Photos showing the western cut slope. Scarping appears to be occurring. Rule 1002.f. is not waivable per Rule 1001.c.; comply with Rule 1002.f. and stabilize cut slopes.



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

Inspection Photos

Operator Name: Matrix Oil Company #10402

Location ID: 428755



**Photo 4:** Photo showing exposed roots (yellow arrow) on the western cut slope, indicating erosion and degradation.



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

## Inspection Photos

Operator Name: Matrix Oil Company #10402

Location ID: 428755



**Photo 5:** Photos showing an example of common mullein, a List C noxious weed, is present throughout the location. Weed management is required per Rules 606.c. and 1004.e.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: Matrix Oil Company #10402

Location ID: 428755



**Photo 6:** Photos showing an example of young thistle basal rosettes, likely Canada thistle (a List B noxious weed), that is present throughout the location. Weed management is required per Rules 606.c. and 1004.e.



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

## Inspection Photos

Operator Name: Matrix Oil Company #10402

Location ID: 428755



**Photo 7:** Photos showing an example of whitetop and thistle rosettes, likely Canada thistle (both a List B noxious weed), that are present throughout the location. Weed management is required per Rules 606.c. and 1004.e.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: Matrix Oil Company #10402

Location ID: 428755



**Photo 8:** Photos showing the access road; the location has a pending Variance request (Docket #220700196) to leave the access road unreclaimed.



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

## Inspection Photos

Operator Name: Matrix Oil Company #10402

Location ID: 428755



**Photo 9:** Photos showing an example of equipment at the location that was purchased/stored by the Surface Owner. Operator has submitted a bill of sale.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources