

# INSPECTION PHOTOS

Well: VPR C 138

API #: 05-071-09056

INSPECTION DOC #: 716302212

Operator: WAPITI OPERATING LLC 10351

Inspection date: 4/21/2026

County: Las Animas



800-574-0696

EMERGENCY CALL 911

WAPITI OPERATING, LLC 575-445-6767

VPR C 138

NW SE, SEC. 2-T35S-R67W

LAS ANIMAS COUNTY, CO

API #05-071-09056-00

EMERG. #575-445-6767


Network: Apr 21, 2026 at 11:56:50 AM MDT  
Local: Apr 21, 2026 at 11:56:50 AM MDT  
+37.023261, -104.856423

PHOTO 2: WELL SIGN



Network: Apr 21, 2026 at 11:55:07 AM MDT  
Local: Apr 21, 2026 at 11:55:07 AM MDT  
+37.023525, -104.856667

PHOTO 3: LOCATION.



Network: Apr 21, 2026 at 11:55:27 AM MDT  
Local: Apr 21, 2026 at 11:55:27 AM MDT  
+37.023351, -104.856388

PHOTO 4: WELLHEAD AND EQUIPMENT.