

Interim Reclamation and Stormwater Inspection

April 16, 2026

Operator: KP KAUFFMAN COMPANY INC - 46290

Location ID: 333129

Well Name: BURKHARDT SELTZER #1

Inspection Document #: 718601595

Weld County, CO

Anthony Dunnam
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: BURKHARDT SELTZER #1
Location ID: 333129



Photo 1. Looking east down the access road.



Photo 2. Looking east across the location. A pile of rocks is stored on location. Undesirable weeds such as kochia are present throughout the location and touching equipment.



Inspection Photos
Location Name: BURKHARDT SELTZER #1
Location ID: 333129



Photo 3. North across the pumpjack. Weeds are in contact with the equipment.



Photo 4. Looking south at the pumpjack. Sign on location.



Inspection Photos
Location Name: BURKHARDT SELTZER #1
Location ID: 333129



Photo 5. Looking west across the interim area. Interim area is reflective of the surrounding vegetation.



Photo 6. Looking east across the location. See photo 5 comments.