

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
404495040  
Receive Date:  
04/20/2026  
Report taken by:  
Grace Rollins

Site Investigation and Remediation Workplan (Supplemental Form)

This form shall be submitted to the Director for approval prior to the initiation of site investigation and remediation activities. However, this shall not preclude the Operator from taking immediate action to protect public health or safety, the environment, wildlife, or livestock.

This Form 27 describes site conditions as currently understood by the Operator; approval of this Form 27 by ECOM is based on the site conditions accurately described herein; any changes in site conditions identified during or subsequent to the performance of the approved workplan may necessitate additional investigation or remediation which shall be described on a supplemental Form 27.

This Form 27 is intended to provide basic information regarding the proposed site investigation and remediation actions, but the workplan may be more fully described in attached documentation.

Closure request is not available for an Initial Site Investigation and Remediation Workplan.

OPERATOR INFORMATION

Name of Operator: <u>NOBLE ENERGY INC</u>	Operator No: <u>100322</u>	Phone Numbers Phone: <u>(970) 304-5000</u> Mobile: <u>( )</u>
Address: <u>1099 18TH STREET SUITE 1500</u>		
City: <u>DENVER</u>	State: <u>CO</u>	Zip: <u>80202</u>
Contact Person: <u>Lauren Hoff</u>	Email: <u>rbueuf27@chevron.com</u>	

PROJECT, PURPOSE & SITE INFORMATION

PROJECT INFORMATION

Remediation Project #: 22612 Initial Form 27 Document #: 402997550

PURPOSE INFORMATION

- Rule 913.c.(1): Pit or Cuttings Trench closure.
- Rule 913.c.(2): Buried or partially buried vessel closure, which will be by removal.
- Rule 913.c.(3): Remediation of Spill and Releases pursuant to Rule 912.
- Rule 913.c.(4): Land treatment of Oily Waste pursuant to Rule 905.e.
- Rule 913.c.(5): Closure of Centralized E&P Waste Management Facilities pursuant to Rule 907.h.
- Rule 913.c.(6): Remediation of impacted Groundwater pursuant to Rule 915.e.(3).D, and the contaminant concentrations in Table 915-1.
- Rule 913.c.(7): Investigation and remediation of natural gas in soil or Groundwater.
- Rule 913.c.(8): When requested by the Director due to any potential risk to soil, Groundwater, or surface water.
- Rule 913.c.(9): Decommissioning of Oil and Gas Facilities.
- Rule 913.g: Changes of Operator.
- Rule 915.b: Request to leave elevated inorganics in situ.
- Other: \_\_\_\_\_

SITE INFORMATION

Yes Multiple Facilities

Facility Type: <u>PIT</u>	Facility ID: <u>118594</u>	API #: _____	County Name: <u>WELD</u>
Facility Name: <u>WESLEY B. MUSER</u>	Latitude: <u>40.189334</u>	Longitude: <u>-104.641041</u>	
** correct Lat/Long if needed: Latitude: _____		Longitude: _____	
QtrQtr: <u>SESE</u>	Sec: <u>27</u>	Twp: <u>3N</u>	Range: <u>65W</u> Meridian: <u>6</u> Sensitive Area? <u>Yes</u>
Facility Type: <u>WELL</u>	Facility ID: _____	API #: <u>123-19516</u>	County Name: <u>WELD</u>
Facility Name: <u>HSR-MOSER 15-27</u>	Latitude: <u>40.190822</u>	Longitude: <u>-104.648044</u>	
** correct Lat/Long if needed: Latitude: _____		Longitude: _____	
QtrQtr: <u>SWSE</u>	Sec: <u>27</u>	Twp: <u>3N</u>	Range: <u>65W</u> Meridian: <u>6</u> Sensitive Area? <u>Yes</u>

Facility Type: TANK BATTERY	Facility ID: 489428	API #:	County Name: WELD
Facility Name: HSR-Moser T3N-R65W-S27 L1 Tank Battery	Latitude: 40.189152	Longitude: -104.640785	
** correct Lat/Long if needed: Latitude:		Longitude:	
QtrQtr: SESE	Sec: 27	Twp: 3N	Range: 65W Meridian: 6 Sensitive Area? Yes

---

Facility Type: SPILL OR RELEASE	Facility ID: 492091	API #:	County Name: WELD
Facility Name: HSR-Moser T3N-R65W-S27 L1	Latitude: 40.189328	Longitude: -104.640785	
** correct Lat/Long if needed: Latitude:		Longitude:	
QtrQtr: SESE	Sec: 27	Twp: 3N	Range: 65W Meridian: 6 Sensitive Area? Yes

**SITE CONDITIONS**

General soil type - USCS Classifications SP Most Sensitive Adjacent Land Use Cropland

Is domestic water well within 1/4 mile? Yes Is surface water within 1/4 mile? Yes

Is groundwater less than 20 feet below ground surface? No

**Other Potential Receptors within 1/4 mile**

# SITE INVESTIGATION PLAN

## TYPE OF WASTE:

- |  |  |  |
|--|--|--|
| <input checked="" type="checkbox"/> E&P Waste      | <input type="checkbox"/> Other E&P Waste             | <input type="checkbox"/> Non-E&P Waste |
| <input checked="" type="checkbox"/> Produced Water | <input type="checkbox"/> Workover Fluids             | _____                                  |
| <input checked="" type="checkbox"/> Oil            | <input type="checkbox"/> Tank Bottoms                |  |
| <input checked="" type="checkbox"/> Condensate     | <input type="checkbox"/> Pigging Waste               |  |
| <input type="checkbox"/> Drilling Fluids           | <input type="checkbox"/> Rig Wash                    |  |
| <input type="checkbox"/> Drill Cuttings            | <input type="checkbox"/> Spent Filters               |  |
|  | <input type="checkbox"/> Pit Bottoms                 |  |
|  | <input type="checkbox"/> Other (as described by EPA) | _____                                  |

## DESCRIPTION OF IMPACT

Impacted?	Impacted Media	Extent of Impact	How Determined
UNDETERMINED	GROUNDWATER	NA	Laboratory analysis and field screening, if encountered
Yes	SOILS	Refer to Tables and Figures	Laboratory analysis and field screening

## INITIAL ACTION SUMMARY

Description of initial action or emergency response measures take to abate, investigate, and/or remediate impacts associated with E&P Waste.

A desktop review was conducted in regards to a historical pit located in close proximity to the HSR-Moser T3N-R65W-S27 L1 tank battery. Soil samples will be collected in the historical pit location.

Pursuant to ECMC Rule 911, a site investigation was conducted on 10/30/2025 and 10/31/2025 at the HSR-Moser T3N-R65W-S27 L1 Facility and Tank Battery location.

Pursuant to ECMC Rule 911, a site investigation was conducted on 10/30/2025 and 10/31/2025 pertaining to the HSR-MOSER 15-27 flowline removal. Approximately 665' of flowline was removed, and approximately 2,035' of flowline was abandoned-in-place due to field constraints. The ECMC will be updated in a supplemental Form 27, should the remaining portion be removed. So as to not disturb the area of field constraint, soil samples will be taken at the start and endpoint of the flowline where the area exists. Soil samples will also be taken along the flowline any points of material change and/or hammer unions, directional changes, as well as at the bell holes on either side of a waterway, as applicable. The Flowline Pre-Abandonment Notice Document number will be included in a subsequent Form 27.

## PROPOSED SAMPLING PLAN

### Proposed Soil Sampling

Will soil samples be collected as part of this investigation? ( Number, type (grab/composite), analyses, and locations of samples ):

One grab soil sample will be collected at the highest PID field screening location at the former pit. Grab confirmation soil samples were collected from the produced water vessel(s) excavation, beneath the ground oil tank(s), at the risers for the flowline(s) and dumpline(s) of any separator(s). In addition, the on-site dump lines located between the separator and tank battery were removed by pulling from either end. Soil samples were taken along the flowline any points of material change and/or hammer unions, directional changes, as well as at the bell holes on either side of a waterway. Soil samples were analyzed by a certified laboratory for the full extent of Table 915-1, including but not limited to: TPH (total volatile [C6-C10] and extractable [C10-C36] hydrocarbons) organic compounds in soil per ECMC Table 915-1, and EC, SAR, pH, metals, and boron. All samples collected will be analyzed by a certified laboratory using approved ECMC laboratory analysis methods.

### Proposed Groundwater Sampling

Will groundwater samples be collected as part of this investigation? ( Number, analyses, and locations of samples ):

If groundwater is encountered during the site investigation, grab groundwater samples will be collected and analyzed for all organic compounds and inorganic parameters per ECMC Table 915-1.

### Proposed Surface Water Sampling

Will surface water samples be collected as part of this investigation? ( Number, analyses, and locations of samples ):

## Additional Investigative Actions

Additional alternative investigative actions described in attached Site Investigation Plan ( summary ):

Visual inspection at the tank battery area occurred during abandonment activities. Field personnel field screened all disturbed areas using visual and olfactory senses. Additionally, discrete soil samples were collected from the base of the excavation and excavation sidewall in areas most likely to be impacted and exhibiting the highest field screened VOC concentration. A detailed summary of flowline and tank battery decommissioning activities, including field notes, site photos, figures, and laboratory analytical results, is attached to this Form 27.

# SITE INVESTIGATION REPORT

## SAMPLE SUMMARY

### Soil

Number of soil samples collected 12

Number of soil samples exceeding 915-1 3

Was the areal and vertical extent of soil contamination delineated? No

Approximate areal extent (square feet) 300

### NA / ND

-- Highest concentration of TPH (mg/kg) 2000

-- Highest concentration of SAR 5.54

BTEX > 915-1 No

Vertical Extent > 915-1 (in feet) 6

### Groundwater

Number of groundwater samples collected 0

Was extent of groundwater contaminated delineated? Yes

Depth to groundwater (below ground surface, in feet)         

Number of groundwater monitoring wells installed         

Number of groundwater samples exceeding 915-1         

Highest concentration of Benzene (µg/l)         

Highest concentration of Toluene (µg/l)         

Highest concentration of Ethylbenzene (µg/l)         

Highest concentration of Xylene (µg/l)         

Highest concentration of Methane (mg/l)         

### Surface Water

0 Number of surface water samples collected

         Number of surface water samples exceeding 915-1

If surface water is impacted, other agency notification may be required.

## OTHER INVESTIGATION INFORMATION

Were impacts to adjacent property or offsite impacts identified?

Were background samples collected as part of this site investigation?

On 10/31/2025, 7 background soil samples were collected from 2 discrete locations (BKG01-BKG02) adjacent to the flowline and analyzed for metals per ECMC Table 915-1, pH, SAR, EC, and boron. Background soil samples were collected from depths ranging between 0 and 6 feet below ground surface (ft. bgs). The maximum background concentration with 1.25x multiplier applied to arsenic, barium, cadmium, lead, and selenium were calculated to be 2.1 mg/kg, 98.8 mg/kg, 0.20 mg/kg, 6.5 mg/kg, and 0.41 mg/kg. All selenium concentrations detected during decommissioning were below background levels.

Was investigation derived waste (IDW) generated as part of this investigation?

Volume of solid waste (cubic yards)         

Volume of liquid waste (barrels)         

Is further site investigation required?

Based on the analytical results collected during decommissioning, a supplemental site investigation (SSI) will be completed to vertically and horizontally delineate the 1,2,4-trimethylbenzene (TMB), 1,3,5-TMB, naphthalene, TPH, benzo(a)anthracene, 1-methylnaphthalene (M), and 2-M exceedances detected during decommissioning. Additionally, soil samples will be collected at proposed sample location FL01-05, and field screened at proposed sample locations FL01-06-FL01-11. All proposed flowline sample locations were selected based on the approved sampling map attached to the Form 27 Supplemental (ECMC Document #404377113). In accordance with the Form 27 Initial (ECMC Document #402997550), soil sampling will also be completed at the historical pit at proposed soil sample locations PIT01 and PIT02 at a depth of 0 to 0.5'. During the SSI, soil samples will be collected and analyzed for full ECMC Table 915-1 constituents. Concurrently with the SSI, additional background samples will be collected to determine if arsenic, barium, cadmium, and lead are attributed to native soil conditions at the site. The SSI will be completed in accordance with the proposed implementation schedule, and the results of the SSI will be submitted on a subsequent Form 27. A proposed SSI map is attached to this Form 27.

## REMEDIAL ACTION PLAN

Does this Supplemental Form 27A include changes to a previously approved Remedial Action Plan? No

## SOURCE REMOVAL SUMMARY

Describe how source is to be removed.

During initial decommissioning activities, elevated PIDs, hydrocarbon odors and hydrocarbon staining were observed beneath the separator dumphine riser (SEP01-DL@5'). Approximately 10 cubic yards of impacted soil was removed and transported off-site under a signed Noble manifest for disposal at Waste Management – Buffalo Ridge in Keenesburg, CO.

## REMEDICATION SUMMARY

Describe how remediation of existing impacts to soil and groundwater is to be accomplished (i.e. summarize remedial action plan). Provide a brief narrative description including: technical justification, schedule for implementation, estimated time to attain NFA status, plus plans and specifications for the selected remedial action technology.

Analytical results from the October 2025 decommissioning activities indicated that organic compound exceedances were detected above the applicable regulatory screening levels for 1,2,4-TMB, 1,3,5-TMB, naphthalene, TPH, benzo(a)anthracene, 1-M, and 2-M in excess of the Table 915-1 PGSSLs and RSSLs. All metal concentrations detected during decommissioning were below the applicable regulatory screening levels or within 1.25x the maximum background levels, with the exception of arsenic, barium, cadmium, and lead. All soil suitability parameters were within the Soil Suitability Limits or local background levels. Based on decommissioning analytical results, an SSI will be completed to vertically and horizontally delineate the benzo(a)anthracene compound exceedance detected at sample location AST01@0-0.5', and the 1,2,4 TMB, 1,3,5 TMB, naphthalene, TPH, 1-M, and 2-M compound exceedances detected at sample location SEP01-FL@4' during decommissioning. Additionally, soil samples will be collected at proposed sample location FL01-05, and field screened at proposed sample locations FL01-06-FL01-11. All proposed flowline sample locations were selected based on the approved sampling map attached to the Form 27 Supplemental (ECMC Document #404377113). In accordance with the Form 27 Initial (ECMC Document #402997550), soil sampling will also be completed at the historical pit at proposed soil sample locations PIT01 and PIT02 at a depth of 0 to 0.5'. During the SSI, soil samples will be collected and analyzed for full ECMC Table 915-1 constituents. The SSI will be completed in accordance with the attached proposed site investigation map, and proposed sampling plan outlined in the Site Investigation Report section of this Form 27.

**Soil Remediation Summary**

<input type="checkbox"/> <b>In Situ</b> _____ Bioremediation ( or enhanced bioremediation ) _____ Chemical oxidation _____ Air sparge / Soil vapor extraction _____ Natural Attenuation _____ Other _____	<input checked="" type="checkbox"/> <b>Ex Situ</b> Yes _____ Excavate and offsite disposal If Yes: Estimated Volume (Cubic Yards) _____ 10 Name of Licensed Disposal Facility or ECMC Facility ID # _____ _____ Excavate and onsite remediation _____ Land Treatment _____ Bioremediation (or enhanced bioremediation) _____ Chemical oxidation _____ Other _____
--	---

**Groundwater Remediation Summary**

\_\_\_\_\_ Bioremediation ( or enhanced bioremediation )  
 \_\_\_\_\_ Chemical oxidation  
 \_\_\_\_\_ Air sparge / Soil vapor extraction  
 \_\_\_\_\_ Natural Attenuation  
 \_\_\_\_\_ Other \_\_\_\_\_

**GROUNDWATER MONITORING**

If groundwater has been impacted, describe proposed monitoring plan, including # of wells or sample points, monitoring schedule, analytical methods, points of compliance. Attach a groundwater monitoring location diagram.

Groundwater was not encountered during initial decommissioning activities.

# REMEDIATION PROGRESS UPDATE

## PERIODIC REPORTING

### Approved Reporting Schedule:

Quarterly     Semi-Annually     Annually     Other

### Request Alternative Reporting Schedule:

Semi-Annually     Annually     Other

Rule 913.e:

After initial approval of a Form 27, the Operator will provide quarterly update reports in a Supplemental Form 27 to document progress of site investigation and remediation, unless an alternative reporting schedule has been requested by the Operator and approved by the Director. The Director may request a more frequent reporting schedule based on site-specific conditions.

**Report Type:**     Groundwater Monitoring     Land Treatment Progress Report     O&M Report

Other Decommissioning Sample Summary & Supplemental Site Investigation Proposal

## Adequacy of Operator's General Liability Insurance and Financial Assurance

Describe the adequacy of the Operator's general liability insurance and Financial Assurance to fully address the anticipated costs of Remediation, including the estimated remaining cost for this project (below).

If this information has been provided on a Form 27 within the last 12 months, provide the Document Number of that form.

Noble intends to directly address the costs of remediation at the locations as part of our asset retirement obligation process and operations. Noble has general liability insurance (policies MWZZ 316714 and MWZX316724) and financial assurance in compliance with ECMC rules. Records are available on the ECMC's website. The cost for remediation is an estimate only, costs may change upwards or downward based on site-specific information. Noble makes no representation or guarantees as to the accuracy of the estimate.

Operator anticipates the remaining cost for this project to be: \$ 50000

## WASTE DISPOSAL INFORMATION

Was E&P waste generated as part of this remediation? No

Describe beneficial use, if any, of E&P Waste derived from this remediation project:

Volume of E&P Waste (solid) in cubic yards

E&P waste (solid) description

ECMC Disposal Facility ID #, if applicable:

Non-ECMC Disposal Facility:

Volume of E&P Waste (liquid) in barrels

E&P waste (liquid) description

ECMC Disposal Facility ID #, if applicable:

Non-ECMC Disposal Facility:

# REMEDIATION COMPLETION REPORT

## REMEDIATION COMPLETION SUMMARY

Is this a Final Closure Request for this Remediation Project? No

If YES:

Compliant with Rule 913.h.(1).

Compliant with Rule 913.h.(2).

Compliant with Rule 913.h.(3).

Do all soils meet Table 915-1 standards? No

Does the previous reply indicate consideration of background concentrations?

Does Groundwater meet Table 915-1 standards? Yes

Is additional groundwater monitoring to be conducted? \_\_\_\_\_

Operator shall comply with the ECMC 1000-Series Reclamation Requirements for all impacted and disturbed areas.

## RECLAMATION PLAN

### RECLAMATION PLANNING

Describe reclamation plan. Discuss existing and new grade recontouring; method and testing of compaction alleviation; and reseeded program, including location of new seed, seed mix and noxious weed prevention. Attach diagram or drawing.

If disturbance occurs reclamation will be in accordance with ECMC 1000 series rules.

Is the described reclamation complete? Yes

Does the reclamation described herein constitute interim or final reclamation of the Oil and Gas Location?

Interim  Final

Did the Surface Owner provide the seed mix? \_\_\_\_\_

If YES, does the seed mix comply with local soil conservation district recommendations? \_\_\_\_\_

Did the local soil conservation district provide the seed mix? \_\_\_\_\_

### SITE RECLAMATION DATES

Proposed date of commencement of Reclamation. 10/30/2025

Proposed date of completion of Reclamation. 11/14/2027

## IMPLEMENTATION SCHEDULE

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

### PRIOR DATES

Date of Surface Owner notification/consultation, if required. 10/31/2025

Actual Spill or Release date, or date of discovery. 10/30/2025

### SITE INVESTIGATION DATES

Date of Initial Actions described in Site Investigation Plan (start date). 10/30/2025

Proposed site investigation commencement. 05/14/2026

Proposed completion of site investigation. 05/14/2026

### REMEDIAL ACTION DATES

Proposed start date of Remediation. 05/14/2026

Proposed date of completion of Remediation. 05/14/2027

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

Change from approved implementation schedule per Rule 913.d.(2).

Basis for change in implementation schedule:

The implementation schedule has been changed due to the decommissioning of the HSR-Moster 15-27 Flowline and HSR-Moser T3N-R65W-S27 L1 Tank Battery and necessity for SSI activities adjacent to the flowline and tank battery. The proposed SSI will be completed following the approval of this form and is tentatively scheduled for commencement on 05/14/2026.

## OPERATOR COMMENT

This Form 27 is being submitted to include the decommissioning results & historic reportable release discovered & propose supplemental site investigation (SSI) activities at the former HSR-Moser 15-27 flowline location & former HSR-Moser T3N-R65W-S27 L1 tank battery location.

Flowline & tank battery decommissioning activities occurred at the above referenced location on October 30, 2025 & October 31, 2025. Discrete soil samples were collected from beneath the former facility infrastructure as described in the approved Form 27 Supplemental (ECMC Document #404377113). Analytical results indicated that soil samples AST01@0-0.5' exhibited benzo(a)anthracene concentrations in exceedance of regulatory standards & SEP01-FL@4' exhibited 1,2,4 trimethylbenzene (TMB), 1,3,5 TMB, naphthalene, TPH, 1-methylnaphthalene (M), & 2-M concentrations in exceedance of the regulatory standards. Elevated arsenic, barium, cadmium, & lead in exceedance of the applicable regulatory screening levels were recorded in the soil sample collected along the flowline (FL01-04@6') & in the soil sample collected beneath the above ground storage tanks (AST01@0-0.5'). Groundwater was not encountered during initial decommissioning activities.

On 10/31/2025, 7 background soil samples were collected from 2 discrete locations (BKG01-BKG02) adjacent to the flowline & analyzed for metals per ECMC Table 915-1, pH, SAR, EC, & boron. Background soil samples were collected from depths ranging between 0 & 6 feet below ground surface (ft. bgs). The maximum background concentration with 1.25x multiplier applied to arsenic, barium, cadmium, lead, & selenium were calculated to be 2.1 mg/kg, 98.8 mg/kg, 0.20 mg/kg, 6.5 mg/kg, & 0.41 mg/kg. All selenium concentrations detected during decommissioning were below background levels.

The following information is included in accordance with the COAs on the Form 19 #s 404418517 & 404418563:

- Reportable release location SEP01-DL: The nearest wetlands (Riverine) is 1570 ft east of the location, as mapped on the National Wetland Inventory Maps & the nearest indication of livestock is 2590 ft north of the location, as visible in aerial imagery.
- Reportable release location FL01R-W: The nearest wetlands (Riverine) is 3610 ft east of the location, as mapped on the National Wetland Inventory Maps & the nearest indication of livestock is 3020 ft northeast of the location, as visible in aerial imagery.

The COA on the returned to draft Form 27 #404495040 is addressed by including Pit ID 118594 in the Site Information & including sample depths for the proposed pit samples.

Based on decommissioning analytical results, an SSI will be completed to vertically & horizontally delineate the benzo(a)anthracene compound exceedance detected at sample location AST01@0-0.5', & the 1,2,4-TMB, 1,3,5-TMB, naphthalene, TPH, 1-M, & 2-M compound exceedances detected at SEP01-FL@4'. Additionally, soil samples will be sampled at proposed sample location FL01-12, & field screened at proposed sample locations FL01-05-FL01-11. All proposed flowline sample locations were selected based on the approved sampling map attached to the Form 27 Supplemental (ECMC Document #404377113). In accordance with the Form 27 Initial (ECMC Document #402997550), soil sampling will also be completed at the historical pit at proposed soil sample locations PIT01 & PIT02 at a depth of 0 to 0.5'. During the SSI, soil samples will be collected & analyzed for full ECMC Table 915-1 constituents. Concurrently with the SSI, additional background samples will be collected to determine if elevated arsenic, barium, cadmium, & lead are attributed to native soil conditions at the site. The SSI will be completed in accordance with the proposed implementation schedule. The proposed soil boring locations are illustrated on the attached proposed site investigation plan.

Pursuant to Rule 913e, quarterly reporting will be conducted until closure criteria are achieved for the remediation project.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: Collin Barker

Title: Environmental Consultant

Submit Date: 04/20/2026

Email: tas-chevron-1@tasman-geo.com

Based on the information provided herein, this Application for Site Investigation and Remediation Workplan complies with ECMC Rules and applicable orders and is hereby approved.

ECMC Approved: Grace Rollins

Date: 04/21/2026

Remediation Project Number: 22612

### COA Type

### Description

	<p>ECMC does not approve this workplan regarding the historic pit(s). Per Document # 697636 ("App for Permit to use Pit [best copy avail]", under Pit Facility ID 118594), one of the former pits measured 12'x8' with an illegible depth. Based on the reported capacity of 102 bbls (equivalent to 573 cubic ft), the depth was likely approximately 6' (12'x 8'x6' = 576 cubic ft). Therefore, sample collection depths of 0-0.5' are inadequate to characterize the historic pits.</p> <p>Operator proposed in Form Initial Form 27 Document # 402997550: "A site assessment will be completed at this location. A soil bore will be advanced to approximately 20' bgs. A grab soil sample will be collected at the highest PID field screening location and will be documented on a bore log."</p> <p>Operator shall ensure borings are advanced to depths adequate to fully characterize conditions which remain in situ. Operator shall provide boring logs in accordance with standard environmental practices. This includes at a minimum; lithology description, USCS classifications, PID readings, sample collection depths, and if applicable depth to water.</p>
	<p>Pursuant to Rule 913.d, Operator will adhere to the proposed schedule. Any deviation from the schedule must be approved by the Director in writing on a Form 27 Supplemental Report.</p>

	Operator will provide the Form 44 Document number for Abandonment Verification submitted pursuant to Rule 1105.f.(2) that includes the requirements of Rule 1105.e. for abandonment in place. This Remediation Project will not be resolved until the flowline has been removed and/or permanently abandoned in place pursuant to Rule 1105.d.(2) and 1105.e.
3 COAs	

**ATTACHMENT LIST**

Upon approval, the approved Form 27 and all listed attachments will be indexed to the Remediation Project file. Only the approved Form 27 will also be indexed to the related Facilities.

<b><u>Att Doc Num</u></b>	<b><u>Name</u></b>
404495040	FORM 27-SUPPLEMENTAL-SUBMITTED
404495043	LABORATORY ANALYTICAL REPORT
404495044	LABORATORY ANALYTICAL REPORT
404495045	LABORATORY ANALYTICAL REPORT
404495047	LABORATORY ANALYTICAL REPORT
404501731	SITE INVESTIGATION PLAN
404501733	SITE INVESTIGATION REPORT
404502093	SITE INVESTIGATION PLAN

Total Attach: 8 Files

**General Comments**

<b><u>User Group</u></b>	<b><u>Comment</u></b>	<b><u>Comment Date</u></b>
Environmental	Operator submitted on 1/21/2026, ECMC returned to draft on 4/20/2026: Pit Facility ID 118594 has been erroneously removed; please correct this omission and resubmit. Please also include additional details regarding the planned pit assessment [i.e. expected total depth of boring(s), interval(s) to be sampled, etc.].	04/07/2026

Total: 1 comment(s)