

Inspection Photos

Location Name: LARAMIE ENERGY LLC Cascade Creek (CC) 0697-15-08 Pad

Location # 481743



Photo # 1365 From entrance to location



Photo # 1366 Sign at entrance to location

Inspection Photos

Location Name: LARAMIE ENERGY LLC Cascade Creek (CC) 0697-15-08 Pad

Location # 481743




Photo # 1367 Battery signage



Photo # 1368 Location

Inspection Photos

Location Name: LARAMIE ENERGY LLC Cascade Creek (CC) 0697-15-08 Pad

Location # 481743



Photo # 1369 Location



Photo # 1370 Location

Inspection Photos

Location Name: LARAMIE ENERGY LLC Cascade Creek (CC) 0697-15-08 Pad

Location # 481743



Photo # 1371 Location



Photo # 1372 Location

Inspection Photos

Location Name: LARAMIE ENERGY LLC Cascade Creek (CC) 0697-15-08 Pad

Location # 481743



Photo # 1373 Location



Photo # 1374 Location

Inspection Photos

Location Name: LARAMIE ENERGY LLC Cascade Creek (CC) 0697-15-08 Pad

Location # 481743



Photo # 1375 Location



Photo # 1376 Location

Inspection Photos

Location Name: LARAMIE ENERGY LLC Cascade Creek (CC) 0697-15-08 Pad

Location # 481743



Photo # 1377 Location



Photo # 1378 Location

Inspection Photos

Location Name: LARAMIE ENERGY LLC Cascade Creek (CC) 0697-15-08 Pad

Location # 481743



Photo # 1379 Location



Photo # 1380 Location

Inspection Photos

Location Name: LARAMIE ENERGY LLC Cascade Creek (CC) 0697-15-08 Pad

Location # 481743



Photo # 1381 Location



Photo # 1382 Location

Inspection Photos

Location Name: LARAMIE ENERGY LLC Cascade Creek (CC) 0697-15-08 Pad

Location # 481743




Photo # 1383 Location



Photo # 1384 Location

Inspection Photos

Location Name: LARAMIE ENERGY LLC Cascade Creek (CC) 0697-15-08 Pad

Location # 481743



Photo # 1385 Cuttings/E & P waste has migrated onto location/not in compliance with CECMC Rules



Photo # 1386 Cuttings/E & P waste has migrated onto location/not in compliance with CECMC Rules

Inspection Photos

Location Name: LARAMIE ENERGY LLC Cascade Creek (CC) 0697-15-08 Pad

Location # 481743



Photo # 1387 Cuttings/E & P waste has migrated onto location/not in compliance with CECMC Rules

Photo # 1388 Cuttings

Inspection Photos

Location Name: LARAMIE ENERGY LLC Cascade Creek (CC) 0697-15-08 Pad

Location # 481743



Photo # 1389 Cuttings/E & P waste has migrated onto & across location/not in compliance with CECMC Rules



Photo # 1390 Cuttings/E & P waste has migrated onto & across location/not in compliance with CECMC Rules

Inspection Photos

Location Name: LARAMIE ENERGY LLC Cascade Creek (CC) 0697-15-08 Pad

Location # 481743



Photo # 1391 Cuttings/E & P waste has migrated onto & across location/not in compliance with CECMC Rules

Photo # 1392 Cuttings/E & P waste has migrated onto & across location/not in compliance with CECMC Rules

Inspection Photos

Location Name: LARAMIE ENERGY LLC Cascade Creek (CC) 0697-15-08 Pad

Location # 481743



Photo # 1393 Cuttings/E & P waste has migrated onto & across location/not in compliance with CECMC Rules



Photo # 1394 Cuttings/E & P waste has migrated onto & across location/not in compliance with CECMC Rules

Inspection Photos

Location Name: LARAMIE ENERGY LLC Cascade Creek (CC) 0697-15-08 Pad

Location # 481743



Photo # 1395 Cuttings/E & P waste has migrated onto & across location/not in compliance with CECMC Rules

Photo # 1396 Cuttings/E & P waste has migrated onto & across location/not in compliance with CECMC Rules

Inspection Photos

Location Name: LARAMIE ENERGY LLC Cascade Creek (CC) 0697-15-08 Pad

Location # 481743



Photo # 1397 Cuttings/E & P waste has migrated onto & across location/not in compliance with CECMC Rules



Photo # 1398 Cuttings/E & P waste has migrated onto & across location/not in compliance with CECMC Rules

Inspection Photos

Location Name: LARAMIE ENERGY LLC Cascade Creek (CC) 0697-15-08 Pad

Location # 481743



Photo # 1399 Cuttings/E & P waste has migrated onto & across location/not in compliance with CECMC Rules



Photo # 1400 Cuttings/E & P waste has migrated onto & across location/not in compliance with CECMC Rules

Inspection Photos

Location Name: LARAMIE ENERGY LLC Cascade Creek (CC) 0697-15-08 Pad

Location # 481743



Photo # 1401 Cuttings/E & P waste has migrated onto & across location/not in compliance with CECMC Rules



Photo # 1402 Cuttings/E & P waste has migrated onto & across location/not in compliance with CECMC Rules

Inspection Photos

Location Name: LARAMIE ENERGY LLC Cascade Creek (CC) 0697-15-08 Pad

Location # 481743



Photo # 1403 Cuttings/E & P waste has migrated onto & across location/not in compliance with CECMC Rules



Photo # 1404 Cuttings/E & P waste has migrated onto & across location/not in compliance with CECMC Rules

Inspection Photos

Location Name: LARAMIE ENERGY LLC Cascade Creek (CC) 0697-15-08 Pad

Location # 481743



Photo # 1405 Staining on location



Photo # 1406 Staining on location

Inspection Photos

Location Name: LARAMIE ENERGY LLC Cascade Creek (CC) 0697-15-08 Pad

Location # 481743



Photo # 1407 Staining on location