

Final Reclamation Inspection

April 16, 2026

Operator: MAGPIE OPERATING INC - 52530

Location ID: 307164

Inspection Document #: 697506113

Larimer County, CO

Chris Binschus
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: PROSPECT LAND CO. 1



Apr 16, 2026 13:36:16
ECMC Reclamation

Photo 1. Photo taken from the entrance of location, facing East. Photo illustrates the access road remains. It appears the surface owner is utilizing the road to access their property.



Apr 16, 2026 13:36:13
ECMC Reclamation

Photo 2. Photo taken from the entrance of location, facing West. See comments under Photo 1.

Inspection Photos

Location Name: PROSPECT LAND CO. 1



Photo 3. Photo taken from the tank battery, facing West. Final reclamation initiated with observed perennial desirable vegetation but is not reflective of reference areas. No noxious weeds observed. Tank battery below red-dashed line.



Photo 4. Photo taken from the tank battery, facing Southwest. See comments under Photo 1.



Inspection Photos

Location Name: PROSPECT LAND CO. 1



Photo 5. Photo taken from the tank battery, facing South. See comments under Photo 1.



Photo 6. Photo taken from the tank battery, facing Southeast. See comments under Photo 1.

Inspection Photos

Location Name: PROSPECT LAND CO. 1



Apr 16, 2026 13:27:41
EGMC Reclamation

Photo 7. Photo taken from the tank battery, facing East. See comments under Photo 1.



Apr 16, 2026 13:34:32
EGMC Reclamation

Photo 8. Reference photo taken west of the tank battery, facing East. Red arrow indicated the approximate tank battery location.

Inspection Photos

Location Name: PROSPECT LAND CO. 1



Photo 9. Photo taken from the well location, facing East. Final reclamation initiated with observed perennial desirable vegetation but is not reflective of reference areas. No noxious weeds observed. Well location below red-dashed line.



Photo 10. Photo taken from the well location, facing North. Photo illustrates portions of the well location are being disturbed by private property accessing adjacent pastures.



Inspection Photos

Location Name: PROSPECT LAND CO. 1



Apr 16, 2026 13:33:54
ECMC Reclamation

Photo 11. Photo taken from the well location, facing East. See comments under Photos 9 and 10.



Apr 16, 2026 13:33:59
ECMC Reclamation

Photo 12. Photo taken from the well location, facing Southwest. Photo illustrates the access road continues south and north to access private property.

Photos 13 and 14 taken from the red arrow.

Inspection Photos

Location Name: PROSPECT LAND CO. 1



Photo 13. Photo illustrates the access road continues south to access private property.



Photo 14. Photo illustrates the access road continues north to access private property.

Inspection Photos
Location Name: PROSPECT LAND CO. 1



Photo 15. Aerial imagery illustrates private properties associated with the surface owner. Red “x’s” illustrate the approximate well location and tank battery.

