

State of Colorado
Energy & Carbon Management Commission



Document Number:
404630740

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Date Received:
04/22/2026

FIR RESOLUTION FORM

Overall Status:

CA Summary:
3 of 3 CAs from the FIR responded to on this Form
3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10749
Name of Operator: SIMCOE LLC
Address: 1199 MAIN AVE SUITE 101
City: DURANGO State: CO Zip: 81301
Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
<u>Kosola, Jason</u>		<u>jason.kosola@state.co.us</u>
<u>Blair, Jamie</u>		<u>jamie.blair@state.co.us</u>
<u>Natural, Mach</u>		<u>ehsinspections@machnr.com</u>
<u>Labowskie, Steve</u>		<u>steve.labowskie@state.co.us</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 721100323
Inspection Date: 04/16/2026 FIR Submit Date: 04/20/2026 FIR Status:

Inspected Operator Information:

Company Name: SIMCOE LLC Company Number: 10749
Address: 1199 MAIN AVE SUITE 101
City: DURANGO State: CO Zip: 81301

LOCATION - Location ID: 325502

Location Name: RICHARDSON-N35N8W Number: 25NWSE County: LA PLATA
Qtrqtr: NWSE Sec: 25 Twp: 35N Range: 8W Meridian: N
Latitude: 37.271374 Longitude: -107.694787

FACILITY - API Number: 05-067-00 Facility ID: 214903

Facility Name: RICHARDSON Number: 01-25 1
Qtrqtr: NWSE Sec: 25 Twp: 35N Range: 8W Meridian: N
Latitude: 37.271374 Longitude: -107.694787

CORRECTIVE ACTIONS:

1 CA# 212303

Corrective Action: If it's determined more than 1 bbl E&P waste was released operator is required submit Form 19 per 900 series rules and contact SW EPS Jason Kosola. Date: 04/22/2026

Response: CA COMPLETED Date of Completion: 04/22/2026

No Form 19 required. Liquid on surface was trucked in water and not any release from wellbore.

Operator Comment: _____

ECMC Decision: _____

ECMC Representative: _____

2 CA# 212304

Corrective Action: Clean up stained soil and dispose of in approved facility to comply with 1002.f.(2).D. Date: 04/22/2026

Response: CA COMPLETED Date of Completion: 04/22/2026

Operator Comment: All stained soil removed off location.

ECMC Decision: _____

ECMC Representative: _____

3 CA# 212305

Corrective Action: Sweep area and remove remove and dispose of all trash to comply with 606.d. Date: 04/22/2026

Response: CA COMPLETED Date of Completion: 04/22/2026

Operator Comment: All trash removed off site.

ECMC Decision: _____

ECMC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: Location cleaned up and equipment removed after rig de-mobe. Location to be handed over to Reclamation Team for final P&A reclamation.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Matthew Baca Signed: _____

Title: Regulatory/Compliance Date: 4/22/2026 3:41:24 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
404630763	Equipment strip and site clean up

Total Attach: 1 Files