

# Final Reclamation Inspection

April 3, 2026

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 330797

Inspection Document #: 718801561

Weld County, CO

Katelyn Mitchem  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: BRATTAIN L #12-12Ji  
Location ID: 330797



**Photo 1.** Photo taken of the well location, facing north. Photo illustrates that final reclamation activities appear to have taken place at the location, but vegetation establishment does not meet Rule 1004 standards.



**Photo 2.** Photo taken of the well location, facing east. See comments under Photo 1.

Inspection Photos  
Location Name: BRATTAIN L #12-12Ji  
Location ID: 330797



**Photo 3.** Photo taken of the well location, facing south. See comments under Photo 1.



**Photo 4.** Photo taken of the well location, facing west. See comments under Photo 1.



Inspection Photos  
Location Name: BRATTAIN L #12-12Ji  
Location ID: 330797



**Photo 5.** Photo taken of ground cover at the location. Photo illustrates perennial grass, bare ground, and weedy annual vegetation including kochia (*Bassia scoparia*) and russian thistle (*Salsola tragus*).



**Photo 6.** Photo taken of the access road to the well location, facing north. Photo illustrates that the access road does not appear to have been recontoured properly and bare ground and weedy annual vegetation including kochia (*Bassia scoparia*) and russian thistle (*Salsola tragus*) were observed.

Inspection Photos  
Location Name: BRATTAIN L #12-12Ji  
Location ID: 330797



**Photo 7.** Photo taken of the access road to the well location, facing north. See comments under Photo 6.



**Photo 8.** Photo taken of the reference area to the location, east of the well location, facing east. Photo illustrates perennial grass.

