

Final Reclamation Inspection

April 3, 2026

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 311469

Inspection Document #: 718801570

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: BRATTAIN L #12-14JI
Location ID: 311469



Photo 1. Photo taken of the well location, facing north. Photo illustrates that final reclamation activities appear to have taken place at the location, but vegetation establishment does not meet Rule 1004 standards and weedy annual vegetation including russian thistle (*Salsola tragus*) and cheatgrass (*Bromus tectorum*), a List C Noxious Weed species, was observed at the location.



Photo 2. Photo taken of the well location, facing east. See comments under Photo 1.



Inspection Photos
Location Name: BRATTAIN L #12-14JI
Location ID: 311469



Photo 3. Photo taken of the well location, facing south. See comments under Photo 1.



Photo 4. Photo taken of the well location, facing west. See comments under Photo 1.

Inspection Photos
Location Name: BRATTAIN L #12-14JI
Location ID: 311469



Photo 5. Photo taken of ground cover at the well location. Photo illustrates perennial grass, bare ground, and weedy annual vegetation including russian thistle (*Salsola tragus*) and cheatgrass (*Bromus tectorum*).



Photo 6. Photo taken of the access road to the location, facing north, away from the location. Photo illustrates that the access road does not meet Rule 1004 standards and bare ground and weedy annual vegetation including cheatgrass (*Bromus tectorum*), a List C Noxious Weed species, were observed.

Inspection Photos
Location Name: BRATTAIN L #12-14JI
Location ID: 311469



Photo 7. Photo taken of the reference area to the location, east of the well location, facing east. Photo illustrates perennial grass and weedy annual vegetation.

