

Final Reclamation Inspection

April 3, 2026

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 328218

Inspection Document #: 718801559

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: BELL #L12-13
Location ID: 328218



Photo 1. Photo taken of the well location, facing north. Photo illustrates that final reclamation activities appear to have taken place at the location, but vegetation establishment does not meet Rule 1004 standards.



Photo 2. Photo taken of the well location, facing east. See comments under Photo 1.

Inspection Photos
Location Name: BELL #L12-13
Location ID: 328218



Photo 3. Photo taken of the well location, facing south. See comments under Photo 1.



Photo 4. Photo taken of the well location, facing west. See comments under Photo 1.



Inspection Photos
Location Name: BELL #L12-13
Location ID: 328218



Photo 5. Photo taken of ground cover at the location. Photo illustrates perennial grass, bare ground, and debris that was observed at the location.



Photo 6. Photo taken of the location, facing southeast. See comments under Photo 1.

Inspection Photos
Location Name: BELL #L12-13
Location ID: 328218



Photo 7. Photo taken of the access road to the well location, facing north. Photo illustrates that reclamation activities appear to have taken place along the road, but vegetation has not established to Rule 1004 standards.



Photo 8. Photo taken of the reference area to the location, east of the well location, facing east. Photo illustrates perennial grass.

