

# Final Reclamation Inspection

April 3, 2026

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 311372

Inspection Document #: 718801568

Weld County, CO

Katelyn Mitchem  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: BELL #L12-14  
Location ID: 311372



**Photo 1.** Photo taken of the well location, facing north. Photo illustrates that final reclamation activities appear to have taken place at the location, but vegetation establishment does not meet Rule 1004 standards and weedy annual vegetation including cheatgrass (*Bromus tectorum*), a List C Noxious Weed species, was observed at the location.



**Photo 2.** Photo taken of the well location, facing east. See comments under Photo 1.

Inspection Photos  
Location Name: BELL #L12-14  
Location ID: 311372



**Photo 3.** Photo taken of the well location, facing south. See comments under Photo 1. Photo illustrates that the access road to the location does not meet Rule 1004 standards and bare ground remains.



**Photo 4.** Photo taken of the well location, facing west. See comments under Photo 1.

Inspection Photos  
Location Name: BELL #L12-14  
Location ID: 311372



**Photo 5.** Photo taken of the well location, facing northeast. See comments under Photo 1.



**Photo 6.** Photo taken of ground cover at the well location. Photo illustrates bare ground and perennial grass.



Inspection Photos  
Location Name: BELL #L12-14  
Location ID: 311372



**Photo 7.** Photo taken of the reference area to the location, southeast of the well location, facing east. Photo illustrates perennial grass and weedy annual vegetation.

