

Final Reclamation Inspection

April 3, 2026

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 317611

Inspection Document #: 718801566

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: BRATTAIN #1
Location ID: 317611



Photo 1. Photo taken of the well location, facing north. Photo illustrates that final reclamation activities appear to have taken place at the location, but vegetation establishment does not meet Rule 1004 standards.



Photo 2. Photo taken of the well location, facing east. See comments under Photo 1.

Inspection Photos
Location Name: BRATTAIN #1
Location ID: 317611



Photo 3. Photo taken of the well location, facing south. See comments under Photo 1.



Photo 4. Photo taken of the well location, facing west. See comments under Photo 1.

Inspection Photos
Location Name: BRATTAIN #1
Location ID: 317611



Photo 5. Photo taken of the well location, facing northwest. See comments under Photo 1.



Photo 6. Photo taken of the access road to the well location, facing north, towards the well location. Photo illustrates that the access road does not meet Rule 1004 standards as weedy annual vegetation including cheatgrass (*Bromus tectorum*), a List C Noxious Weed species, was observed along the road.



Inspection Photos
Location Name: BRATTAIN #1
Location ID: 317611



Photo 7. Photo taken of the tank battery location, facing northeast. Photo illustrates that final reclamation activities appear to have taken place, but vegetation has not established to Rule 1004 standards and gravel remains on the location. Weedy annual vegetation including cheatgrass (*Bromus tectorum*), a List C Noxious Weed species, was observed at the location.



Photo 8. Photo taken of the tank battery location, facing east. See comments under Photo 7.

Inspection Photos
Location Name: BRATTAIN #1
Location ID: 317611



Photo 9. Photo taken of the tank battery location, facing south. See comments under Photo 7.



Photo 10. Photo taken of the tank battery location, facing west. See comments under Photo 7.

Inspection Photos
Location Name: BRATTAIN #1
Location ID: 317611



Photo 11. Photo taken of ground cover at the tank battery location. Photo illustrates perennial grass, bare ground, gravel, and weedy annual vegetation including cheatgrass (*Bromus tectorum*), a List C Noxious Weed species.



Photo 12. Photo taken of the reference area to the location, east of the well location, facing east. Photo illustrates perennial grass and weedy annual vegetation.