

Final Reclamation Inspection

April 3, 2026

Operator: NOBLE ENERGY INC - 100322

Location ID: 328328

Inspection Document #: 718801574

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: BELL #L12-24
Location ID: 328328



Photo 1. Photo taken of the well location, facing north. Photo illustrates that final reclamation activities appear to have taken place, with evidence of drill row seeding, but vegetation establishment does not meet Rule 1004 standards.



Photo 2. Photo taken of the well location, facing east. See comments under Photo 1.

Inspection Photos
Location Name: BELL #L12-24
Location ID: 328328



Photo 3. Photo taken of the well location, facing south. See comments under Photo 1.



Photo 4. Photo taken of the well location, facing west. See comments under Photo 1.



Inspection Photos
Location Name: BELL #L12-24
Location ID: 328328



Photo 5. Photo taken of the well location, facing northeast. See comments under Photo 1. Photo illustrates debris was observed across the northeastern portion of the location (circled in red).



Photo 6. Photo taken of ground cover at the location. Photo illustrates perennial grass, weedy annual vegetation, and debris.

Inspection Photos
Location Name: BELL #L12-24
Location ID: 328328



Photo 7. Photo taken of the access road to the well location, facing east, towards the location. Photo illustrates that final reclamation activities appear to have taken place, with evidence of drill rows from seeding, but vegetation establishment does not meet Rule 1004 standards.



Photo 8. Photo taken of the access road to the well location, facing east. Photo illustrates debris was observed on the road.

Inspection Photos
Location Name: BELL #L12-24
Location ID: 328328



Photo 9. Photo taken of the reference area to the location, north of the location, facing east. Photo illustrates perennial grass and weedy annual vegetation.

