

INSPECTION PHOTOS

Well: ART 44-32

API #: 05-071-08007

INSPECTION DOC #: 716302225

Operator: EVERGREEN NATURAL RESOURCES LLC

Inspection date: 4/24/2026

County: Las Animas



Network: Apr 24, 2026 at 10:16:51 AM MDT
Local: Apr 24, 2026 at 10:16:51 AM MDT
+37 208474 -104 687731

PHOTO 2: WELL SIGN



Network: Apr 24, 2026 at 10:16:26 AM MDT
Local: Apr 24, 2026 at 10:16:26 AM MDT
+37.208410, -104.688016

PHOTO 3: LOCATION.



Network: Apr 24, 2026 at 10:17:04 AM MDT
Local: Apr 24, 2026 at 10:17:04 AM MDT
+37.208369, -104.687670
4048 S

PHOTO 4: TR WELLHEAD AND EQUIPMENT.