

INSPECTION PHOTOS

Well: BOXSTER 12-23 & TR

API #: 05-071-07164 & 9123

INSPECTION DOC #: 716302223

Operator: EVERGREEN NATURAL RESOURCES LLC

Inspection date: 4/23/2026

County: Las Animas



EVERGREEN
NATURAL RESOURCES LLC
 BOXSTER 12-23
 API 05-071-07164
 SW NW SECTION 23-32S-66W
 WDID 1910155 / Permit # 71493
 EMERGENCY No. 911 or 719-846-7898 (24 Hrs)

LAT. 37.24631 / LONG. -104.7552
 WDID 1910155 / Permit # 71493-F
 COC59968A

EVERGREEN
NATURAL RESOURCES LLC
 BOXSTER 12-23 TR
 API 05-071-09123
 SW NW SECTION 23-32S-66W
 CR 51
 LAT. 37.24625/LONG. -104.7549
 EMERGENCY No. 911 or 719-846-7898 (24 Hrs)
 WDID 1910460 / Permit # 72514

WDID 1910460 / Permit # 72514-F
 COC59968A

Network: Apr 23, 2026 at 10:32:44 AM MDT
 Local: Apr 23, 2026 at 10:32:44 AM MDT
 +37 246356 -104 755023

PHOTO 2: WELL SIGN



Network: Apr 23, 2026 at 10:28:07 AM MDT
Local: Apr 23, 2026 at 10:28:07 AM MDT
+37.246119, -104.754834

PHOTO 3: LOCATION.



PHOTO 4: ORIG. WELLHEAD AND EQUIPMENT.




PHOTO 5: TR WELLHEAD AND EQUIPMENT.



Network: Apr 23, 2026 at 10:29:06 AM MDT
Local: Apr 23, 2026 at 10:29:06 AM MDT
+37 246315 -104 755228
0718 W

PHOTO 6: TRASH (INSULATION FROM ORIGINAL WELLHEAD PRODUCTION LINE IS TORN AND THERE ARE SMALL PIECES ALL AROUND LOCATION). REMOVE ALL TRASH AND SECURE THE INSULATION ON THE WELLHEAD PER RULE 606. CA DATE 4/28/2026.



PHOTO 7: MORE IMAGES OF TRASH AROUND LOCATION.



PHOTO 8: MORE IMAGES OF TRASH AROUND LOCATION.



PHOTO 9: MORE IMAGES OF TRASH AROUND LOCATION.



PHOTO 10: MORE IMAGES OF TRASH AROUND LOCATION.