

INSPECTION PHOTOS

Well: LPGC 32-32

API #: 05-071-08641

INSPECTION DOC #: 716302227

Operator: EVERGREEN NATURAL RESOURCES LLC

Inspection date: 4/24/2026

County: Las Animas





PHOTO 2: WELL SIGN



Network: Apr 24, 2026 at 10:57:31 AM MDT
Local: Apr 24, 2026 at 10:57:31 AM MDT
+37.216568, -104.692191

PHOTO 3: LOCATION.



Network: Apr 24, 2026 at 10:57:56 AM MDT
Local: Apr 24, 2026 at 10:57:56 AM MDT
+37.216592,-104.691940
106° S

PHOTO 4: WELLHEAD AND EQUIPMENT. UNUSED EQUIPMENT (HEAD FOR PUMPJACK, JUMPJACK FENCING AND WOOD CHOCK ON GROUND NEAR JUMPJACK. **REMOVE OR REINSTALL UNUSED EQUIPMENT PER RULE 606. CA DATE 5/24/2026.**



Network: Apr 24, 2026 at 10:54:08 AM MDT
Local: Apr 24, 2026 at 10:54:08 AM MDT
+37.216014, -104.693145
72° F

PHOTO 5: CULVERT ON ROW JUST OFF COUNTY ROAD IS PLUGGED. CLEAN AND MAINTAIN CULVERT AND DRAINAGE DITCHES PER RULE 1002.f. CA DATE 5/24/2026.



Network: Apr 24, 2026 at 10:54:32 AM MDT
Local: Apr 24, 2026 at 10:54:32 AM MDT
+37.216007, -104.693023
201° SW

PHOTO 6: CULVERT ON ROW JUST OFF COUNTY ROAD IS PLUGGED. CLEAN AND MAINTAIN CULVERT AND DRAINAGE DITCHES PER RULE 1002.f. CA DATE 5/24/2026.



Network: Apr 24, 2026 at 10:55:26 AM MDT
Local: Apr 24, 2026 at 10:55:26 AM MDT
+37.216031, -104.693114
2618'W

PHOTO 7: DRAINAGE DITCH FROM CULVERT ON ROW TO THE CULVERT THAT CHANELS STORMWATER UNDER COUNTY ROAD IS SILTED IN. CLEAN AND MAINTAIN CULVERT AND DRAINAGE DITCHES PER RULE 1002.f. CA DATE 5/24/2026.