

# Final Reclamation and Stormwater Inspection

April 24, 2026

Operator: PETROLEUM INC - 69450

Location ID: 401046

Well Name: KRAL #A-2

Inspection Document #: 718601607

Washington County, CO

Anthony Dunnam  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: KRAL #A-2  
Location ID: 401046



**Photo 1.** Looking west across the location. A concrete pumpjack pad remains on the location. The location is within a fallow field.



**Photo 2.** Looking east across the location. See photo 2 comments.



Inspection Photos  
Location Name: KRAL #A-2  
Location ID: 401046



**Photo 3.** Looking north from the well location.



**Photo 4.** Looking south from the well location.