

This is a BATTERY audit.

Well(s): 3: Temporarily Abandoned | TA.

Battery: Inactive | Shut-down.

Centralized Battery serves 3 Location IDs

(309818, 309820, 309841).

(Well(s): 3: Temporarily Abandoned | TA).

Centralized Battery formerly served 3 Location IDs

(309819, 410006, 430376).

(Well(s): 8: Plugged & Abandoned | PA).

Centralized Battery serves 1 Tank Battery Facility ID

(Pending).

Reference (Associated Well(s), Battery / Facility Audits):

A.) Field Audit Report doc. #719700649 and/or Location ID #309818 for TA Well(s) info.

B.) Field Audit Report doc. #719700651 and/or Location ID #309820 for TA Well(s) info.

C.) Field Audit Report doc. #719700653 and/or Location ID #309841 for TA Well(s) info.

D.) Field Audit Report doc. #719700655 and/or Location ID #309819 for PA Well(s) info.

E.) Field Audit Report doc. #719700657 and/or Location ID #410006 for PA Well(s) info.

F.) Field Audit Report doc. #719700659 and/or Location ID #430376 for PA Well(s) info.

G.) Field Audit Report doc. #719700661 and/or Location ID #309818 for Battery / Facility, Equipment info.

*This is an audit of the scout card and related documents followed by a field audit.

Location

| | | | |
|--------------------|----------|--|-------|
| Lease Road: | | | |
| Type | Access | | |
| comment: | Adequate | | |
| Corrective Action: | | | Date: |

Overall Good:

| | | | |
|----------------------|---------------------------------|--|-------|
| Signs/Marker: | | | |
| Type | BATTERY | | |
| Comment: | OOSLAT applied at separator(s). | | |
| Corrective Action: | | | Date: |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment:

Multiple Spills and Releases?

| | | | |
|--------------------|---|--|-------|
| Fencing/: | | | |
| Type | SEPARATOR | | |
| Comment: | Barbed wire. Surrounded by earth berms. | | |
| Corrective Action: | | | Date: |
| Type | TANK BATTERY | | |
| Comment: | Barbed wire. | | |
| Corrective Action: | | | Date: |

| | | | |
|-----------------------------------|--|--|-----------------|
| Equipment: | | | corrective date |
| Type: Gas Meter Run | # 1 | | |
| Comment: | Gas Sales, Master; (Phillips 66). Calibration card(s) indicates calibration >1 year. Last calibration: 02/02/2024. Inactive. | | |
| Corrective Action: | | | Date: |
| Type: Vertical Separator | # 1 | | |
| Comment: | Shut-down. Inactive. | | |
| Corrective Action: | | | Date: |
| Type: Horizontal Heated Separator | # 1 | | |
| Comment: | Shut-down. Inactive. | | |

| | |
|--------------------|-------|
| Corrective Action: | Date: |
|--------------------|-------|

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|---|---|----------|---------------------|---------|--------|
| | | | CENTRALIZED BATTERY | | |
| Comment: Centralized Battery serves 3 Location IDs (309818, 309820, 309841). (Well(s): 3: Temporarily Abandoned TA). Centralized Battery serves 1 Tank Battery Facility ID (Pending). | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | |
|------------------|--|
| Condition | |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| | | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|----------------|---------|--------|
| PRODUCED WATER | 3 | OTHER | PBV FIBERGLASS | | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | |
|------------------|-----------|
| Condition | |
| Other (Content) | |
| Other (Capacity) | 150 Bbls. |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--|----------|---------------------|---------------------|-------------|
| Earth | Adequate | Walls Sufficent | Base Sufficient | Adequate |
| Comment: Berms shared w/ condensate, produced H2O tank(s). | | | | |
| Corrective Action: | | | | Date: |

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|-----------------------|
| CONDENSATE | 9 | 300 BBLS | STEEL AST | | 40.373587,-104.476895 |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | |
|------------------|----------|
| Condition | Adequate |
| Other (Content) | |
| Other (Capacity) | |

| | |
|--------------------|--|
| Other (Type) _____ | |
|--------------------|--|

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--|----------|---------------------|---------------------|-------------|
| Earth | Adequate | Walls Sufficent | Base Sufficent | Adequate |
| Comment: Berms shared w/ condensate, produced H2O tank(s). | | | | |
| Corrective Action: | | | | Date: |

Wells Served By Facilities Above

| API Number |
|------------|
| 123-25421 |
| 123-25446 |
| 123-25424 |

AirsID

| API Number | AirsID |
|------------|--------|
| | |

Venting:

| Yes/No | NO | | |
|--------------------|----|--|-------|
| Comment: | | | |
| Corrective Action: | | | Date: |

Flaring:

| Type | | |
|--------------------|--|-------|
| Comment: | | |
| Corrective Action: | | Date: |

Inspected Facilities

Facility ID: 309818 Type: LOCATION API Number: - Status: AC Insp. Status: IO

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: Well(s): 3: Temporarily Abandoned | TA. Battery Inactive.

Corrective Action: Date:

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel | Pass | Gravel | Pass | | | |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

| Comment | User | Date |
|--|--------|------------|
| <p>CECMC Audit Report Synopsis:</p> <p>On TUE 04/21/2026 at approximately 16:33 hrs. I, Bret Evins, conducted an onsite audit at: Operator Name: HIGHPOINT OPERATING CORPORATION Facility Name: Pending Facility ID: Pending Location Name: PETERSON-65N63W/30SWNE Location ID: 309818 Well Name(s): See photo(s) #6, 7 attached to this report. API: See "Wells Served By Facilities Above" sec of this report and/or photo(s) #7 attached to this report. Location County: Weld County, Colorado Weather: Mostly Sunny, dry.</p> <p>While there, I observed: Well(s): 3: Temporarily Abandoned TA. Battery: Inactive Shut-down.</p> <p>Routine audit.</p> <p>*Any Corrective Actions from prior audits that have not been addressed remain applicable.</p> | evinsb | 04/24/2026 |

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------|---|
| 719700662 | Audit photo(s) | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7526495 |