

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 22B-1 Pad

Location #: 324253



Photo # 2029 From entrance to location




Photo # 2030 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 22B-1 Pad

Location #: 324253



Photo # 2031 Location



Photo # 2032 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 22B-1 Pad

Location #: 324253




Photo # 2033 Location




Photo # 2034 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 22B-1 Pad

Location #: 324253



Photo # 2035 Weeds in secondary containment



Photo # 2036 Weeds in secondary containment

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 22B-1 Pad

Location #: 324253




Photo # 2037 API # on wellhead sign incorrect