

# Inspection Photos

April 20th, 2026

Operator: Hilcorp Energy Co.

Location ID: 325300

Inspection Document #: 714003565

County: La Plata

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

April 20, 2026 at 11:02 AM  
162° S



**Photo 1.** View of the well pad taken from the access point facing center.

April 20, 2026 at 11:04 AM  
163° S



**Photo 2.** View of deep gully erosion persisting on the southern edge of the pad.

April 20, 2026 at 11:05 AM  
341° N



**Photo 3.** View of location cutslope which remains with minimal vegetation and bare loose soils.

Inspection Photos  
Location Name: Squires 1, 4



**Photo 4.** Drone aerial of the location. Note: Location does not meet interim reclamation vegetation standards and active erosion occurring on southern edge of location.