

Inspection Photos

April 20th, 2026

Operator: Simcoe LLC

Location ID: 333539

Inspection Document #: 714003567

County: La Plata

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Moffett B1

April 20, 2026 at 12:13 PM
293° NW



Photo 1. View of the location taken from the southern edge facing north.

Inspection Photos
Location Name: Moffett B1

April 20, 2026 at 12:14 PM
310° NW



Photo 2. Secondary containment ring installed around produced water tank.



Inspection Photos
Location Name: Moffett B1



Photo 3. Patch of Musk Thistle rosettes observed on location.