

Inspection Photos

April 20th, 2026

Operator: Simcoe LLC

Location ID: 333811

Inspection Document #: 714003568

County: La Plata

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Spanish Fork A1, A3

April 20, 2026 at 12:15 PM
25° NE



Photo 1. View of the location taken from the southern edge facing north.

Inspection Photos
Location Name: Spanish Fork A1, A3

April 20, 2026 at 12:15 PM
291° W



Photo 2. Patch of Musk thistle on the western edge of the pad.

Inspection Photos
Location Name: Spanish Fork A1, A3



Photo 3. Patch of Musk Thistle rosettes observed on location.