

# Inspection Photos

April 20th, 2026

Operator: Morningstar Operating

Location ID: 333344

Inspection Document #: 714003563

County: Archuleta

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Quintana



**Photo 1.** View of well pad taken from the access point facing center.  
Note: local emergency number has been posted.

April 20, 2026 at 9:53 AM  
256° W



**Photo 2.** Wattles installed are no longer functioning.



Inspection Photos  
Location Name: Quintana

April 20, 2026 at 9:54 AM  
11° N



**Photo 3.** Trash/debris has been removed from the edge of the pad.

Inspection Photos  
Location Name: Quintana

April 20, 2026 at 9:52 AM  
205° SW



**Photo 4.** No weeds observed in the southwest corner of the location.

