

INSPECTION PHOTOS

Well: BOXSTER 12-23 & TR

API #: 05-071-07164 & 9123

INSPECTION DOC #: 716302223

Operator: EVERGREEN NATURAL RESOURCES LLC

Inspection date: 4/23/2026

County: Las Animas



PHOTO 2: WELL SIGN



PHOTO 3: LOCATION.




PHOTO 4: ORIG. WELLHEAD AND EQUIPMENT.



Network Apr 23, 2026 at 10:28:30 AM MDT
Local Apr 23, 2026 at 10:28:31 AM MDT
+37.246237, -104.754986
54° N

PHOTO 5: TR WELLHEAD AND EQUIPMENT.



PHOTO 6: TRASH (INSULATION FROM ORIGINAL WELLHEAD PRODUCTION LINE IS TORN AND THERE ARE SMALL PIECES ALL AROUND LOCATION). **REMOVE ALL TRASH AND SECURE THE INSULATION ON THE WELLHEAD PER RULE 606. CA DATE 4/28/2026.**



PHOTO 7: MORE IMAGES OF TRASH AROUND LOCATION.



PHOTO 8: MORE IMAGES OF TRASH AROUND LOCATION.



PHOTO 9: MORE IMAGES OF TRASH AROUND LOCATION.



PHOTO 10: MORE IMAGES OF TRASH AROUND LOCATION.