

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/27/2026

Submitted Date:

04/27/2026

Document Number:

719001831

FIELD INSPECTION FORM

Loc ID: 326679 Inspector Name: GARCIA, CHARLES On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10749
 Name of Operator: SIMCOE LLC
 Address: 1199 MAIN AVE SUITE 101
 City: DURANGO State: CO Zip: 81301

Findings:

4 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
		ehsinspections@machnr.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
262344	WELL	PR	01/10/2002	CBM	067-08679	GEARHART 01-06 2	PR

General Comment:

Inspection Report Summary
 On 3/3/26 I Inspector Charles Garcia conducted an desktop follow up inspection.
 Location: GEARHART 01-06 #2
 Operator: Simcoe LLC
 API#: 067-08679
 County: LaPlata
 All prior CA's still stand
 DOC#719001491
 FIR#404626371
 CA RESOLVED

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type	Equipment	Quantity	Corrective Action	Corrective Date
Compressor	# 1	1		
	Comment: OIL LEAK ON COMPRESSOR ENGINE IMPACTED SOIL AROUND ENGINE SKID AND SOUTH SIDE OF SOUND WALL SEE LOCATION PICTURES Corrective Action: MAINTAIN ENGINE RULE 608.e AND CLEAN UP IMPACTED SOIL AROUND COMPRESSOR rule 1002.f CA RESOLVED			
	Corrective Action:			Date: _____

Venting:

Yes/No	Comment	Corrective Action	Date

Flaring:

Type	Comment	Corrective Action	Date

Inspected Facilities

Facility ID: 262344 Type: WELL API Number: 067-08679 Status: PR Insp. Status: PR

BradenHead

Date of Last Brhd Test: 08/20/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: PR

Corrective Action: _____

Date: _____

ECMC Comments

Comment	User	Date
CA RESOLVED SEE FIR DOC#404626371	garcia1	04/27/2026