

# INSPECTION PHOTOS

Well: JOHN K 12-28

API #: 05-071-08723

INSPECTION DOC #: 716302237

Operator: EVERGREEN NATURAL RESOURCES LLC

Inspection date: 4/27/2026

County: Las Animas




PHOTO 2: WELL SIGN



Network: Apr 27, 2026 at 1:13:13 PM MDT  
Local: Apr 27, 2026 at 1:13:13 PM MDT  
+37.232188,-104.684704

PHOTO 3: LOCATION.



PHOTO 4: WELLHEAD AND EQUIPMENT.



Network Apr 27, 2026 at 1:15:29 PM MDT  
Local Apr 27, 2026 at 1:15:29 PM MDT  
+37 232361-104 684748  
71°F

**PHOTO 5: DRY GRASS OVERGROWN IN CENTER OF LOCATION AND NEAR METER HOUSE SHOULD BE MAINTAINED.**