

# Inspection Photos

04/16/2026

**Operator:** Caerus Piceance LLC #10456

**Location ID:** 398469

**Inspection Doc:** 719201067

Rio Blanco County, CO

Emily Gaasche  
NW Reclamation Specialist  
ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: Caerus Piceance LLC #10456

Location ID: 398469



**Photo 1:** Photos showing an overview of the location looking north and south, respectively. Location does not appear to meet 1004 uniformity requirement.



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

## Inspection Photos

Operator Name: Caerus Piceance LLC #10456

Location ID: 398469



**Photo 2:** Photos showing an overview of the location looking east and west, respectively. Location does not appear to meet 1004 uniformity requirement.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: Caerus Piceance LLC #10456

Location ID: 398469



**Photo 3:** Photos showing that Canada thistle at the location has been treated; no new rosettes or weeds were observed.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: Caerus Piceance LLC #10456

Location ID: 398469



**Photo 4:** Photos showing a general overview of the location looking west and north, respectively.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: Caerus Piceance LLC #10456

Location ID: 398469



**Photo 5:** Photos showing the nearby reference area, located in the same pasture directly west of the location. The pasture is composed of mixed pasture grasses.



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources