

# Inspection Photos

API: 071-08131

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 4/27/2026

County: LAS ANIMAS



## Inspection Photos



**Photo 1.** Facing west along the access road. The road has been graded and maintained.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

API:071-08131 | Date: 4/27/2026

## Inspection Photos



**Photo 2.** Facing west along the access road. The culverts are cleaned out and maintained.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

API:071-08131 | Date: 4/27/2026

## Inspection Photos



**Photo 3.** Facing west toward the well site.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

API:071-08131 | Date: 4/27/2026