

# Inspection Photos

API: 071-08354

Operator: EVERGREEN NATURAL  
RESOURCES LLC

Inspection Date: 4/27/2026

County: LAS ANIMAS



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing southeast along the access road. The ae of erosion has been repaired and culvert maintained.



## Inspection Photos



**Photo 2.** Facing east along the access road. This culvert has been cleaned out.



## Inspection Photos



**Photo 3.** Facing northwest toward the wellsite.



## Inspection Photos



**Photo 4.** Facing northwest toward the wellsite.

