

Inspection Photos  
Location Name: SCHIMPH 11-23 #1  
Location ID: 320308



**PHOTO#1 GAS METER/AUTOMATION RTU/SEPARATOR**



**PHOTO#2 PRODUCTION TANKS**

Inspection Photos  
Location Name: SCHIMPH 11-23 #1  
Location ID: 320308



**PHOTO#4 WELLHEAD**