

Audit Photos

Location Name: VISION ENERGY LLC, CAMP GULCH UNIT-FEDERAL-68S103W/24SESE

Location ID: 312579

Date: 4/21/2026



Location Overview – Photo #03572



Location/Weeds – Photo #03573

Audit Photos

Location Name: VISION ENERGY LLC, CAMP GULCH UNIT-FEDERAL-68S103W/24SESE

Location ID: 312579

Date: 4/21/2026



Apr 21, 2026 at 15:00:12
+39.341497,-108.828598
2196 6 1/2 Rd
Loma CO 81525
United States



Apr 21, 2026 at 15:01:23
+39.341386,-108.828494
2196 6 1/2 Rd
Loma CO 81525
United States

Location/Unused Equipment/Weeds – Photo #03575


Location – Photo #03581

Audit Photos

Location Name: VISION ENERGY LLC, CAMP GULCH UNIT-FEDERAL-68S103W/24SESE

Location ID: 312579

Date: 4/21/2026



Apr 21, 2026 at 15:00:54
+39.341461,-108.828554
2196 6 1/2 Rd
Loma CO 81525
United States



Apr 21, 2026 at 15:01:10
+39.341401,-108.828554
2196 6 1/2 Rd
Loma CO 81525
United States

Location/Weeds/Trash – Photo #03578

Open-Ended Line – Photo #03579

Audit Photos

Location Name: VISION ENERGY LLC, CAMP GULCH UNIT-FEDERAL-68S103W/24SESE

Location ID: 312579

Date: 4/21/2026



Open-Ended Line – Photo #03580



Unserviceable Tank Labeling – Photo #03582