

Inspection Photos

April 24th, 2026

Operator: Simcoe LLC

Location ID: 325941

Inspection Document #: 714003586

County: La Plata

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Litton Federal 1



Photo 1. 2025 aerial view of the location (highlighted in blue) and associated access road (highlighted in red).

Inspection Photos
Location Name: Litton Federal 1

April 24, 2026
141° SE



Photo 2. View of location access road facing towards the pad which remains unreclaimed with gravel.



Inspection Photos
Location Name: Litton Federal 1

April 24, 2026
66° NE



Photo 3. View of well pad; surface equipment has been removed but pad remains unreclaimed with gravel and has not been recontoured.

Inspection Photos
Location Name: Litton Federal 1



Photo 4. Temporary BMPs installed appear to be in working condition.

Inspection Photos
Location Name: Litton Federal 1

April 24, 2026
223° SW



Photo 5. View of well pad taken from the northern edge facing southwest.