

Inspection Photos

April 24th, 2026

Operator: Simcoe LLC

Location ID: 385860

Inspection Document #: 714003584

County: La Plata

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Pole Barn Monitor Well 1



Photo 1. View of the project area taken from the western edge facing center.



Inspection Photos
Location Name: Pole Barn Monitor Well 1

April 24, 2026
1° N



Photo 2. Cardinal photo taken from the center of the project area facing north.

Inspection Photos
Location Name: Pole Barn Monitor Well 1



Photo 3. Cardinal photo taken from the center of the project area facing south.

Inspection Photos
Location Name: Pole Barn Monitor Well 1



Photo 4. View of southern portion of the project area. Note: two track remains for access to pole barn to the north.



Inspection Photos
Location Name: Pole Barn Monitor Well 1

April 24, 2026
4° N



Photo 5. Adjacent reference areas.