

Inspection Photos

April 24th, 2026

Operator: Simcoe LLC

Location ID: 325933

Inspection Document #: 714003585

County: La Plata

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Gurr Federal Gas Unit 1

April 24, 2026
272° W



Photo 1. View of the location taken from the access point facing center.

Inspection Photos
Location Name: Gurr Federal Gas Unit 1

April 24, 2026
280° W



Photo 2. View of interim reclamation area.



Inspection Photos
Location Name: Gurr Federal Gas Unit 1



Photo 3. Wellhead assembly equipment; vegetation encroaching on equipment.