

# Inspection Photos

April 24th, 2026

Operator: Simcoe LLC

Location ID: 325535

Inspection Document #: 714003580

County: La Plata

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Couch 01-16U 1



Photo 1. View of the location taken from the access point facing center.

Inspection Photos  
Location Name: Couch 01-16U 1

April 24, 2026  
255° W



**Photo 2.** View of interim reclamation area, weedy debris have been removed.

April 24, 2026  
351° N



**Photo 3.** View of location taken from the southern edge facing center.