

Inspection Photos

April 24th, 2026

Operator: Simcoe LLC

Location ID: 325895

Inspection Document #: 714003583

County: La Plata

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Gearhart B1



Photo 1. View of the location taken from the access point facing center.

Inspection Photos
Location Name: Gearhart B1

April 24, 2026
182° S



Photo 2. View of meter shed and separator equipment, labels are starting to deteriorate/peel.

Inspection Photos
Location Name: Gearhart B1

April 24, 2026
122° SE



Photo 3. View of interim reclamation areas.

