

# Inspection Photos

April 24th, 2026

Operator: Simcoe LLC

Location ID: 326611

Inspection Document #: 714003578

County: La Plata

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Miller Federal 2

April 24, 2026  
289° W



Photo 1. View of the location taken from the access point facing center.

Inspection Photos  
Location Name: Miller Federal 2



**Photo 2.** Patches of Canda thistle observed throughout the location.

Inspection Photos  
Location Name: Miller Federal 2



**Photo 3.** Culvert at access point is starting to fill with sediment.

Inspection Photos  
Location Name: Miller Federal 2



April 24, 2026  
219° SW

**Photo 4.** Access point gate pole is rotting and beginning to fall.

