

Inspection Photos

04/22/2026

Operator: Robert L. Bayless Producer LLC
#6720

Location ID: 313019

Inspection Doc: 719201078

Moffat County, CO

Emily Gaasche
NW Reclamation Specialist
ECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: Robert L. Bayless Producer LLC #6720

Location ID: 313019



Photo 1: Photos showing an overview of the location looking north and south, respectively.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: Robert L. Bayless Producer LLC #6720

Location ID: 313019



Photo 2: Photos showing an overview of the location looking east and west, respectively. Vegetation at the central portion of the location is not uniform.



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: Robert L. Bayless Producer LLC #6720

Location ID: 313019



Photo 3: Photos showing an example of houndstongue rosettes, a List B noxious weed, is present throughout the location. Weed maintenance is required.



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: Robert L. Bayless Producer LLC #6720

Location ID: 313019



Photo 4: Photos showing an example of thistle skeletons that are present throughout the location. No new thistle growth was observed; however, ongoing weed monitoring and maintenance is required.



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: Robert L. Bayless Producer LLC #6720

Location ID: 313019



Photo 5: Photos showing a subsidence feature appears to be present at the south-central portion of the location. Maintenance is required to stabilize the area; comply with Rule 1002.f.



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: Robert L. Bayless Producer LLC #6720

Location ID: 313019



Photo 6: Photos showing the access road leading to the location has not been reclaimed pursuant to 1004 series Rules.



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: Robert L. Bayless Producer LLC #6720

Location ID: 313019



Photo 7: Photo showing fencing trash/debris that requires removal.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: Robert L. Bayless Producer LLC #6720

Location ID: 313019



Photo 8: Photos showing portions of downed perimeter fencing around the location. Maintenance is required.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: Robert L. Bayless Producer LLC #6720

Location ID: 313019



Photo 9: Photos showing the nearby reference area; located directly west of the site. The reference area is a big sagebrush flat near a scrub-oak transition zone.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources