

INSPECTION PHOTOS

Well: DRAGON 42-33

API #: 05-071-06704

INSPECTION DOC #: 716302248

Operator: EVERGREEN NATURAL RESOURCES LLC

Inspection date: 4/28/2026

County: Las Animas



PHOTO 2: WELL SIGN IS NOT LEGIBLE FROM A DISTANCE (NEW SIGN IS STORED INSIDE METER HOUSE). **REPLACE SIGN PER RULE 605. CA DATE 4/30/2026.**



Network: Apr 28, 2026 at 1:55:03 PM MDT
Local: Apr 28, 2026 at 1:55:03 PM MDT
+37.217306, -104.668855

PHOTO 3: NEW SIGN STORED INSIDE METER HOUSE.



Network: Apr 28, 2026 at 1:53:50 PM MDT
Local: Apr 28, 2026 at 1:53:50 PM MDT
+37.217118, -104.668499
976° W

PHOTO 4: LOCATION.



Network: Apr 28, 2026 at 1:55:29 PM MDT
Local: Apr 28, 2026 at 1:55:29 PM MDT
+37 217344 -104 668988
896° NW

PHOTO 5: WELLHEAD AND EQUIPMENT.