

INSPECTION PHOTOS

Well: BOWSER 34-21

API #: 05-071-08868

INSPECTION DOC #: 716302260

Operator: EVERGREEN NATURAL RESOURCES LLC

Inspection date: 4/29/2026

County: Las Animas



PHOTO 2: WELL SIGN



Network: Apr 29, 2026 at 12:04:09 PM MDT
Local: Apr 29, 2026 at 12:04:09 PM MDT
+37.238386, -104.676488

PHOTO 3: LOCATION.



Network: Apr 29, 2026 at 12:04:35 PM MDT
Local: Apr 29, 2026 at 12:04:35 PM MDT
+37.238213, -104.676687
026 SW

PHOTO 4: WELLHEAD AND EQUIPMENT.



Network: Apr 29, 2026 at 12:06:07 PM MDT
Local: Apr 29, 2026 at 12:06:07 PM MDT
+37.238101, -104.676746
108° E

PHOTO 5: UNUSED EQUIPMENT (1" RISER NOT IN USE OR USEFUL). REMOVE OR IDENTIFY THE CONTENTS PER RULE 606. CA DATE 5/29/2026.



Network: Apr 29, 2026 at 12:05:53 PM MDT
Local: Apr 29, 2026 at 12:05:53 PM MDT
+37.238086, -104.676665
205° NW

PHOTO 6: UNUSED EQUIPMENT (TWO CONCRETE AND TWO METAL BRACKETS). REMOVE UNUSED EQUIPMENT PER RULE 606. CA DATE 5/29/2026.



Network Apr 29, 2026 at 12:02:35 PM MDT
Local Apr 29, 2026 at 12:02:35 PM MDT
+37.238781, -104.676471
154° SE

PHOTO 7: STORMWATER EROSION AT ENTRANCE OF LOCATION VEHICLES ARE DRIVING OFF OF THE ROW TO BYPASS THE EROSION. IMMEDIATELY STOP ALL VEHICLES FROM DRIVING OFF OF THE ROW AND INSTALL BMP'S TO PREVENT STORMWATER EROSION FROM DAMAGING THE ROW PER RULE 1002. CA DATE 5/5/2026.