

Inspection Photos

04/22/2026

Operator: BONANZA CREEK ENERGY OPERATING
LLC- #8960

Location ID: 324729

Inspection Document #: 712300288

Jackson County, CO

Logan Maxwell
Reclamation Specialist
ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: McCallum Unit #165 Pad
Location ID: 324729



Photo 1. Photos 1-4 taken from the center of the pad disturbance, facing north, east, south, and west, illustrating the Location overview.



Photo 2. See comments under Photo 1.

Inspection Photos
Location Name: Mccallum Unit #165 Pad
Location ID: 324729



Photo 3. See comments under Photo 1.



Photo 4. See comments under Photo 1.

Inspection Photos
Location Name: McCallum Unit #165 Pad
Location ID: 324729



Photo 5. Photo taken of the center of the well pad. The area where the well head was previously is not progressing towards 1004 vegetation standards.



Photo 6. Photo taken east of the well pad center facing west; photo illustrates that areas downhill of the pad center have not established vegetation.

Inspection Photos
Location Name: McCallum Unit #165 Pad
Location ID: 324729



Photo 7. Photos 7-8 illustrate examples of trash/debris left on the Location.



Photo 8. See comments under Photo 7.

Inspection Photos
Location Name: McCallum Unit #165 Pad
Location ID: 324729



Photo 9. Photo illustrates that the anchor marker has been left on Location. It was unclear if the anchors were left on the Location, but have since been buried.



Photo 10. Photo illustrates that the access road has not been reclaimed.

Inspection Photos
Location Name: Mccallum Unit #165 Pad
Location ID: 324729



Photo 11. Photos 11-12 taken east of the Location, facing east and south, illustrating reference area vegetation. This includes primarily Wyoming sagebrush, Sandburg bluegrass, and phlox.



Photo 12. See comment under Photo 11.

