

Inspection Photos

04/22/2026

Operator: BONANZA CREEK ENERGY OPERATING
LLC- #8960

Location ID: 324614

Inspection Document #: 712300295

Jackson County, CO

Logan Maxwell
Reclamation Specialist
ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: McCallum Unit #59 Pad
Location ID: 324614



Photo 1. Photos 1-4 taken from the center of the pad disturbance, facing north, east, south, and west. Photos illustrate that vegetation has established across the pad, including Sandburg bluegrass, rabbitbrush, and sagebrush.



Photo 2. See comments under Photo 1.



Inspection Photos
Location Name: McCallum Unit #59 Pad
Location ID: 324614



Photo 3. See comments under Photo 1.



Photo 4. See comments under Photo 1.

Inspection Photos
Location Name: Mccallum Unit #59 Pad
Location ID: 324614



Photo 5. Photo taken of the reference area vegetation east of the well pad, facing southeast.