

Inspection Photos

API: 073-06488

Operator: GRAND MESA OPERATING CO

Inspection Date: 4/29/2026

County: LINCOLN



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing north along the pre-existing road. It appears this road has been graded since the previous inspection.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:073-06583 | Date: 4/29/2026

Inspection Photos



Photo 2. Facing north along the pre-existing road.



Inspection Photos



Photo 3. Facing southeast along the former access road which has revegetated.



Inspection Photos



Photo 4. Facing southeast along the former access road which has revegetated.



Inspection Photos



Photo 5. Facing southeast toward the location. There is mostly bunch grass vegetation (Rye grass) throughout the location.



Inspection Photos



Photo 6. Center of the location facing east.



Inspection Photos



Photo 7. Center of the location facing west.



Inspection Photos



Photo 8. Facing south at the east side of the location. There are areas bare of vegetation .



Inspection Photos



Photo 9. Facing north at the east side of the location. This area has uniform vegetation cover.



Inspection Photos



Photo 10. Facing east toward the surrounding reference area.



Inspection Photos



Photo 11. Drone aerial photo facing east toward the location.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:073-06583 | Date: 4/29/2026

Inspection Photos



Photo 12. Drone aerial photo facing northwest toward the location.



Inspection Photos



Photo 13. Center of the location facing northwest down at the location.

