

Inspection Photos
Location Name: Magellan 1
API #: 05-043-06229
Location ID: 443255



Photo 1 Well Placard, Well Name is illegible

Photo 2: Wellhead and equipment

Inspection Photos
Location Name: Magellan 1
API #: 05-043-06229
Location ID: 443255



Photo 3: Oily buildup on pumping unit base

Photo 4: Oily buildup and impacts to soils

Inspection Photos
Location Name: Magellan 1
API #: 05-043-06229
Location ID: 443255



Photo 5: Loadout

Photo 6: impacted material within secondary containment