

Inspection Photos

API: 073-06250

Operator: MAGPIE OPERATING INC

Inspection Date: 4/29/2026

County: LINCOLN



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Drone aerial photo facing northeast toward the location.



Inspection Photos



Photo 2. Drone aerial photo facing northeast toward the location. There are still area bare of vegetation shown at red arrows.



Inspection Photos



Photo 3. Drone aerial photo facing north toward the location. There are still areas that have not established desirable vegetation cover.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:073-06250 | Date: 4/29/2026

Inspection Photos



Photo 4. Drone aerial photo facing west toward the location. There are still areas that have not established desirable vegetation cover. The dark areas are bare soils and weeds.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:073-06250 | Date: 4/29/2026