

# INSPECTION PHOTOS

Well: S.E. CAMPO UNIT-602

API #: 05-071-06483

INSPECTION DOC #: 716302266

Operator: MURFIN DRILLING COMPANY INC

Inspection date: 5/1/2026

County: Las Animas



PHOTO 2: WELL SIGN



Network: May 1, 2026 at 1:16:23 PM CDT  
Local: May 1, 2026 at 1:16:23 PM CDT  
+37.028445, -102.555280

PHOTO 3: LOCATION.



Network: May 1, 2026 at 1:17:25 PM CDT  
Local: May 1, 2026 at 1:17:25 PM CDT  
+37.028188, -102.555148  
860° W

**PHOTO 4: UNUSED EQUIPMENT (WELLHEAD FENCING). REMOVE UNUSED EQUIPMENT PER RULE 606. CA DATE 5/15/2026.**



Network May 1, 2026 at 1:17:17 PM CDT  
Local May 1, 2026 at 1:17:17 PM CDT  
+37-028187-102-555073  
1263:1W

**PHOTO 5: TRASH EAST OF LOCATION. REMOVE ALL TRASH ON AND AROUND LOCATION PER RULE 606. CA DATE 5/15/2026.**